



Big Valley Divers Inc.
P O Box 3284
Chico Ca. 95927
Office (530) 898-1110 Fax (530) 893-1836
Cell (530) 521-7797

Customer: Fresno County-WWD 38 (Sky Harbour)
 Address: 2220 Tulare Street 6th Floor, Fresno, CA 93721
 Office (559) 600 -4259 Fax (559) 600-4552 Cell (559) 600-4481
 Rep: Julie Zimmer-Belle
 Re: Sky Harbour Tank Inspection and Cleaning

TANK INSPECTION REPORT

Date	04-03-2018	Water Elevation	
Location	WWD 38	Depth	
	Sky Harbour	Water Temp.	N/A
Requested By		Visibility	4'
Site Forman	Julie Zimmer-Belle	Current (fps)	N/A
Dive Supervisor		Photos Y / N	Y

Tank Builder: N/A
Tank Age: N/A
Tank Capacity Gallons: 120,000 Gallons
Tank Construction: Above Ground, Steel Welded Seam
Tank Diameter: 30'
Tank Height: 23'
Access Ladder Outside: Yes
Access Hatch and Measurements: Round 25" Diameter
Access Ladder Inside: Yes
Electrolysis Protection: N/A
Tank Coating Outside: Yes, Good Condition
Tank Coating Inside Roof: Yes, minor rust, epoxy red
Tank Coating Inside Wall: Yes, major rust
Tank Coating Inside Floor: Unknown, major rust
Structural Repairs Found: None
Structural Damage Found: None
Floor Sediment or Debris: 6"-1'
Overflow Pipe: Yes
Inlet / Outlet Pipes: Yes
Blind Entry / Cleanout Openings: Yes
Tank Drain: Yes
Support Columns: One, middle of tank



Big Valley Divers Inc.
P O Box 3284
Chico Ca. 95927
Office (530) 898-1110 Fax (530) 893-1836
Cell (530) 521-7797


Tank inspection found the epoxy coating on the inside of the tank to be compromised to the point of failure. There is major rust boils on the walls and floor of the tank. The floor appears to not have much coating left with major rust throughout. Tank was cleaned and vacuumed and will need to be drained and repaired by tank contractor. Outside of tank is in good condition. Video was taken and included in report for documentation.

Recommendations:

1- Contact tank contractor to determine if the tank can be repaired or if it needs to be replaced. Reference report and video with tank manufacturer.



Big Valley Divers Inc.
P O Box 3284
Chico Ca. 95927
Office (530) 898-1110 Fax (530) 893-1836
Cell (530) 521-7797



Rust Boils inside tank



Rust in tank



Before vacuuming tank, heavy sediment



Outside of tank-Good Condition



Outside of tank-Good Condition